## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.










FIG. 2






FIG. 3






FIG 4








FIG. 5





F16.6





F16.7







FIG. 8





F16.9






FIG. 10








FIG. 11






F16.12





F16.13





F16.14







Fig. 15








FIG. 16







FIG. 17





F16.18






Fig. 19






FIG. 20



Docket No.: NHL-DEL-01-REG

Appln. No.: 10/601,839 Replacement Sheet





Figure 21




Docket No.: NHL-DÉL-01-REG

Appln. No.: 10/601,839 Replacement Sheet












Docket No.: NHL-DEL-01-REG


Appln. No.: 10/601,839 Replacement Sheet






Air regulator







Wood 1 X 12 X 10



Plastic strip for the lane






Base of the connector for the exit of compressed air

Figure 24







Docket No.: NHL-DEL-01-REG

Appln. No.: 10/601,839 Replacement Sheet

